

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210
Box 145801

Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291

Fax: (801) 359-3940

3/5/05
RECEIVED
JAN 05 2005
DIV. OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/04 To (mo./yr.) 12/04
2. DOGM File Number (Mine No): 5230076
3. Mine Name: Cactus 1 / Serendipity 6 / Cherie 3
4. Mineral(s) Mined (or permitted to mine): Topaz, Hematite
5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, ____ 1/4, NE 1/4, Section 7, Township 14S, Range 10W Cherie #3
____ 1/4, ____ 1/4, SW 1/4, Section 28, Township 12S, Range 11W Cactus #1
____ 1/4, ____ 1/4, SW 1/4, Section 33, Township 11S, Range 11W Serendipity #6
7. Name of Operator or Company: Larry E. Lehto
8. Permanent Street Address: 12868 W. Ellsworth Pl.
City, State, Zip: Lakewood, Co. 80228
Phone: 303-988-7948 Fax: _____
9. Company Representative (or designated operator):
Name: _____
Title: _____
Business Address: _____
City, State, Zip: _____
Phone: _____ Fax: _____
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? No Ore, Mining with Hand Tools

Need to inspect to determine if we can
close out disturbance reclaimed.

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Mining with hand tools; 6 yd.³
No New disturbances

5. How much **additional acreage** was disturbed during the past year? 0

6. How much acreage was **reclaimed** during the past year? 1 acre

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Reclamation of the Cactus #1 and
Seneca dipity #6 was completed during 2004.
pits on Cactus #1 filled in with excavator
pits on Seneca dipity #6 filled in with backhoe

8. What is the **total** disturbed acreage of entire project at years end? 1/2 acre

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Not known at this time

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Larry E. Lehto

Title of Operator: Owner

Signature of Operator: Larry E. Lehto

Date: 1-2-05